

VEHICLE EXAMINATION REPORT



OPERATOR New Forest Executive Travel
 Vehicle Reg No
 Make & Model Audi A8
 Colour Black
 Mileage 49478
 Hackney / Private Hire Plate No New Plate

ELECTRICAL

Lights
 Washer / Wipers
 Horn

INTERIOR

Trim
 Seat belts
 Seats
 Carpets
 Cleanliness

ENGINE

Performance
 Excess wear
 Oil burning
 Emissions

STEERING

Box & Idler
 Rack
 P.A.S.
 Joints & Couplings
 Swivel assemblies
 Gaiters
 Radius Arms, Tie Rods
 Steering wheel
 Steering column
 Wheel bearings
 Bias - Left/Right

EXHAUST SYSTEM

Silencer
 Mounting points
 Leaks

BODYWORK

Cleanliness / Condition
 Chassis

SUSPENSION

Coil springs
 Dampers / Struts
 Mounting rubbers
 Anti-roll Bushes
 Bottom ball joints
 Elip, Springs. Shkls

G/BOX/T'MISSION

Clutch
 Gearbox - Selection
 Transmission noise
 Syncromesh
 Prop-Shaft U/J's
 F.W.D. Shafts
 Final drive
 Auto trans inhib switch

BRAKES

Hydraulic fluid
 Master cylinder
 Pipelines / Unions

Flexible Hoses Discs & Callipers Wheel Cylinders Foot Pedal Travel H'brake Adjustment Servo Equipment Mech Linkages **TYRES**F/O side F/N side R/N side R/O side Spare **GENERAL**Door Locks / Handles Windows Oil Leaks Fire Extinguisher Mirrors Door Step Alarm (A/V) LOLER Lift Test Wheelchair Ramp Wheelchair Restraints Taxi Plate Display HCV Roof Sign Taxi meter tariff Road test **REMARKS / COMMENTS**

Minimum seating capacity requirements not met. (3 passenger seats only)

Advise number plate letter spacing

uld b

RE-TEST* No

IMPORTANT

RECEIPT NO:

This Report refers only to the items listed. Opinions expressed with regard to various items are founded on external examination only, as no dismantling work is carried out. Accordingly, The New Forest District Council cannot accept liability for latent defects.

PASS* No

Examiner Date

